

COPY OF BUILDING SAFETY CERTIFICATE



**ਦਫ਼ਤਰ ਉਪ ਮੰਡਲ ਇੰਜੀਨੀਅਰ, ਪ੍ਰਾਂਤਕ ਉਪ ਮੰਡਲ, ਲੋਕ ਨਿਰਮਾਣ ਵਿਭਾਗ,
ਭਵਨ ਤੇ ਮਾਰਗ, ਸ਼ਾਖਾ, ਮਲੇਰਕੋਟਲਾ**

ਵੱਲ

ਪ੍ਰਿੰਸੀਪਲ,
ਮੋਡਰਨ ਸੈਕੂਲਰ ਪਬਲਿਕ ਸਕੂਲ,
ਸ਼ੇਰਗੜ੍ਹ ਚੀਮਾ, ਮਲੇਰਕੋਟਲਾ।

ਵਿਸ਼ਾ:

ਹਵਾਲਾ:


ਨੰਬਰ 139

ਮਿਤੀ 23/06/2025

ਸਕੂਲ ਦੀ ਬਿਲਡਿੰਗ ਦੇ ਸੇਫਟੀ ਸਰਟੀਫਿਕੇਟ ਸਬੰਧੀ।

ਆਪ ਜੀ ਦਾ ਪੱਤਰ ਨੰ: MSPS/2025 ਮਿਤੀ: 09-06-2025

ਉਪਰੋਕਤ ਵਿਸ਼ੇ ਅਤੇ ਹਵਾਲਾ ਅਧੀਨ ਪੱਤਰ ਦੇ ਸਬੰਧ ਵਿੱਚ ਲਿਖਿਆ ਜਾਂਦਾ ਹੈ ਕਿ ਇਸ ਉਪ ਮੰਡਲ ਦਫ਼ਤਰ ਦੇ ਜੂਨੀਅਰ ਇੰਜੀਨੀਅਰ ਸ਼੍ਰੀ ਮਨਪ੍ਰੀਤ ਸਿੰਘ ਵੱਲੋਂ ਆਪ ਜੀ ਦੇ ਸਕੂਲ ਦਾ ਨਿਰੀਖਣ ਕਰਨ ਉਪਰੰਤ ਰਿਪੋਰਟ ਕੀਤੀ ਗਈ ਹੈ ਕਿ ਬਿਲਡਿੰਗ ਸਾਲ 2025-26 (31-03-2026) ਤੱਕ ਬਾਹਰੋਂ ਵੇਖਣ ਵਿੱਚ ਸੇਫ ਜਾਪਦੀ ਹੈ। ਬਿਲਡਿੰਗ ਵਿੱਚੋਂ ਜੇਕਰ ਕੋਈ ਵੀ ਅਡੀਸ਼ਨਲ ਆਲਟਰੇਸ਼ਨ ਕਰਨੀ ਹੈ ਤਾਂ ਕਿਸੇ ਟੈਕਨੀਕਲ ਕੁਆਲੀਫਾਈਡ ਇੰਜੀਨੀਅਰ ਪਾਸੋਂ ਚੈੱਕ ਕਰਵਾ ਕੇ ਤਸਦੀਕ ਕਰਵਾਇਆ ਜਾਵੇ। ਜੇਕਰ ਹੜ੍ਹ, ਕੁਦਰਤੀ ਆਫ਼ਤ ਨਾਲ ਕੋਈ ਵੀ ਦੀਵਾਰ, ਨੀਂਹਾਂ ਬਰਿੰਦੀਆਂ ਹਨ ਤਾਂ ਉਸ ਬਾਰੇ ਵੀ ਟੈਕਨੀਕਲ ਕੁਆਲੀਫਾਈਡ ਇੰਜੀਨੀਅਰ ਪਾਸੋਂ ਚੈੱਕ ਕਰਵਾਉਣਾ, ਉਪਰੰਤ ਤਸਦੀਕ ਵੀ ਕਰਵਾਇਆ ਜਾਵੇ। ਇਸ ਦੀ ਇੰਸਪੈਕਸ਼ਨ ਫੀਸ ਚਲਾਨ ਨੰ: CPAFGVGN05 ਮਿਤੀ: 23-06-2025 ਰਾਹੀਂ 10,000/- ਰੁਪਏ ਜਮ੍ਹਾਂ ਕਰਵਾ ਲਈ ਗਈ ਹੈ। ਇਸ ਦੇ ਇਲਾਵਾ ਆਪ ਨੂੰ ਹਦਾਇਤ ਕੀਤੀ ਜਾਂਦੀ ਹੈ ਕਿ ਸਕੂਲ ਦਾ ਫਾਇਰ ਸੇਫਟੀ ਸਰਟੀਫਿਕੇਟ ਮਿਤੀ: 28/08/2025 ਤੱਕ ਖਤਮ ਹੋਣ ਉਪਰੰਤ ਰੀਨਿਊ ਕਰਵਾਕੇ ਇਸ ਦਫ਼ਤਰ ਜਮ੍ਹਾਂ ਕਰਵਾਉਣਾ ਯਕੀਨੀ ਬਣਾਇਆ ਜਾਵੇ, ਨਹੀਂ ਤਾਂ ਬਿਲਡਿੰਗ ਸੇਫਟੀ ਸਰਟੀਫਿਕੇਟ ਰੱਦ ਸਮਝਿਆ ਜਾਵੇਗਾ।


ਉਪ ਮੰਡਲ ਇੰਜੀਨੀਅਰ

ਪ੍ਰਾਂਤਕ ਉਪ ਮੰਡਲ ਲੋ:ਨਿ:ਵਿ: ਭ ਤੇ ਮ ਸ਼ਾਖਾ
ਮਲੇਰਕੋਟਲਾ।

ਪਿੱਠ ਅੰਕਣ ਨੰਬਰ:

ਮਿਤੀ:

ਉਪਰੋਕਤ ਦਾ ਉਤਾਰਾ ਕਾਰਜਕਾਰੀ ਇੰਜੀਨੀਅਰ, ਉਸਾਰੀ ਮੰਡਲ, ਲੋਕ ਨਿਰਮਾਣ ਵਿਭਾਗ ਭ ਤੇ ਮ ਸ਼ਾਖਾ, ਮਲੇਰਕੋਟਲਾ ਜੀ ਨੂੰ ਆਪ ਜੀ ਦੇ ਪੱਤਰ ਨੰ: 1230 ਮਿਤੀ: 13-06-2025 ਦੀ ਲਗਾਤਾਰਤਾ ਵਿੱਚ ਸੂਚਨਾ ਹਿੱਤ ਭੇਜਿਆ ਜਾਂਦਾ ਹੈ ਜੀ।

ਨੱਥੀ/ਚਲਾਨ ਕਾਪੀ, ਇੰਸਪੈਕਸ਼ਨ ਪ੍ਰੋਫਾਰਮਾ

ਉਪ ਮੰਡਲ ਇੰਜੀਨੀਅਰ


ਪ੍ਰਾਂਤਕ ਉਪ ਮੰਡਲ ਲੋ:ਨਿ:ਵਿ: ਭ ਤੇ ਮ ਸ਼ਾਖਾ
ਮਲੇਰਕੋਟਲਾ।

Building safety report

**NAME OF SCHOOL: MODERN SECULAR PUBLIC SCHOOL,
SHERGARH CHEEMA, MALERKOTLA.**

As per report of Sh. Manpreet Singh (Junior Engineer) on his visually inspection, the above mentioned school seems visually safe subject to the following observations and conditions:-

1. However, the Parameters to check the stability and safety of building such as Architectural Drawings, Bearing capacity, Foundation details, Structural drawings, Technical Specifications, Test reports of Material used and Quality control reports are not available.
2. In case any addition, alteration, expansion and modification to this building are required to be done, regarding this inspection of undersigned may be arranged and obtained a certificate after the completion from the undersigned.
3. In the case of building is affected by flood or if there is any settlement of walls foundation of roof etc. immediately inspection of the undersigned be arranged to check the stability and safety of the building.
4. A separate certificate regarding Fire Fighting should be obtained from the competent Authority.
5. A separate certificate regarding Electrical works should be obtained be from the competent Authority.
6. The owner of the building/ Management is fully responsible regarding safety of the building from all angles in spite of this report.
7. This report is for the covered area of the building as per Drawing submitted by the owner.
8. This report is not valid for legal purpose.
9. As per visually inspection as reported by the concerned Junior Engineer the above building may be used for normal use for One year up to 31/03/2026 subject to the above conditions.


Sub-Divisional Engineer,
Provl. Sub- Division,
PWD B&R Malerkotla.